

Flame Certificate
Stitch
399618

maharam

Stitch was tested and met the following flammability requirements:
Walls: ASTM E 84 Adhered flame 5, smoke 0

Contact clientservices@maharam.com with any questions.