Flame Certificate Fluted Silk 465982

maharam

Fluted Silk was tested and met the following flammability requirements: Seating: California Bulletin # 117-2013, NFPA 260

 $Contact \ clients ervices @ maharam.com \ with \ any \ questions.$