

Flame Certificate  
Boundary  
466193

**maharam**

Boundary was tested and met the following flammability requirements:  
Seating: California Bulletin #117-2013

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.