

Flame Certificate  
Buffer  
466492

**maharam**

Buffer was tested and met the following flammability requirements:

Seating: California Bulletin #117-2013

Upholstered Walls: ASTM E 84 Unadhered flame 5, smoke 60

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.