

Flame Certificate  
Respite  
283788

**maharam**

Respite was tested and met the following flammability requirements:  
Windows: NFPA 701

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.