

Flame Certificate

Fix

399441

maharam

Fix was tested and met the following flammability requirements:

Walls: ASTM E 84 Adhered flame 25, smoke 5

Contact clientservices@maharam.com with any questions.