

Flame Certificate

INTHEBEGINNINGTIMELIESASAPRESENTINFRONTOFFOURFEET

399460

maharam

INTHEBEGINNINGTIMELIESASAPRESENTINFRONTOFFOURFEET was tested and met the following flammability requirements:

Walls: ASTM E 84 Adhered flame 10, smoke 0

Contact clientservices@maharam.com with any questions.