

Flame Certificate  
Cluster  
399963

**maharam**

Cluster was tested and met the following flammability requirements:  
Walls: ASTM E 84 Adhered flame 15, smoke 120

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.