

Flame Certificate  
Coach Cloth  
458950

**maharam**

Coach Cloth was tested and met the following flammability requirements:  
Seating: California Bulletin # 117-2013, NFPA 260

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.