

Flame Certificate

Tremor
466045

maharam

Tremor was tested and met the following flammability requirements:
Seating: California Bulletin # 117-2013, NFPA 260

Contact clientservices@maharam.com with any questions.