

Flame Certificate
Banister
466263

maharam

Banister was tested and met the following flammability requirements:
Seating: California Bulletin #117-2013

Contact clientservices@maharam.com with any questions.