

# Flame Certificate

Seam

466289

**maharam**

Seam was tested and met the following flammability requirements:

Seating: California Bulletin #117-2013

Upholstered Walls:

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.