

Flame Certificate

Mode

466337

maharam

Mode was tested and met the following flammability requirements:

Seating: California Bulletin # 117-2013, NFPA 260

Contact clientservices@maharam.com with any questions.