

Flame Certificate

Branch

511472

maharam

Branch was tested and met the following flammability requirements:

Privacy Curtain: NFPA 701

Upholstered Walls: ASTM E 84 Unadhered

Windows: NFPA 701

Contact clientservices@maharam.com with any questions.