

Flame Certificate  
Relay  
466453

**maharam**

Relay was tested and met the following flammability requirements:  
Seating: California Bulletin #117-2013  
Upholstered Walls: ASTM E 84 Unadhered flame 5, smoke 130

Contact [clientservices@maharam.com](mailto:clientservices@maharam.com) with any questions.